





TS 5000
TS 5000 S
TS 5000 SoftClose

107934-05




GEZE




5 mm

A














$a \leq 1400 \text{ mm}$


B




$a \leq 1400 \text{ mm}$




1




2




3




4




5




6




7




8




i+ TS 5000 S



i+ TS 5000 SoftClose



9



i

