





TS 5000 Eline
TS 5000 S Eline

144856-03



GEZE



5 mm

A















$a \leq 1250 \text{ mm}$



B




$a \leq 1250 \text{ mm}$




4x
M5x45


1




2




3



4






5



6







5 mm



7





5 mm



i+

TS 5000 S


5 mm



8





5 mm



i

a ≤ 1250 mm



a ≤ 1250 mm

!

a > 1100 mm

